









1. Drill plastic out of the mounting holes on the seat, braces and stands using a 7/16" dia. drill bit.
2. Fasten the seat to the stands loosely, then attach the braces to the seat and stands loosely.
3. Make sure stands, seat and braces are aligned, then tighten all of the bolts.
4. Position bench where desired and mount to surface if desired.

| ITEM NO. | PART NUMBER | DESCRIPTION                             | QTY. |
|----------|-------------|-----------------------------------------|------|
| 1        | 733-013     | Grand Contour Free Standing Bench Stand | 2    |
| 2        | 625-004     | 4' Grand Contour Laser Bench            | 1    |
| 3        | 631-313     | Brace for FS Bench                      | 2    |
| 4        | 516-058     | 3/8"x1-1/2" SS Hex Bolt                 | 4    |
| 5        | 516-033     | 3/8"x4" SS Button Head Cap Screw        | 4    |
| 6        | 516-023     | 3/8" SS Flat Washer                     | 16   |
| 7        | 516-028     | 3/8" SS Nylock Nut                      | 8    |

In Accordance to California law: WARNING This product contains a chemical known to the State of California to cause cancer and birth defects or other reproductive harm.

Periodic check of bolt tightness recommended.