






6' Grand Contour Laser Free Standing/Surface Mount Bench

971-303




ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	733-013	Grand Contour Free Standing/SM Stand with back	2
2	625-005	6' Grand Contour Laser Bench	2
3	631-313A	Grand Contour w\back Brace	2
4	516-033	3/8"x4" SS Button Head Cap Screw	4
5	516-058	3/8"x1-1/2" SS Hex Bolt	4
6	516-028	3/8" SS Nylock Nut	8
7	516-023	3/8" SS Flat Washer	16



PREMIER POLYSTEEL

The Best Commercial Outdoor Furniture Available. Period.





This product uses Hardware Pack HWPK08
(you may receive extra hardware)

4 qty. 3/8" x 1-1/2" SS Hex Bolt

4 qty. 3/8" x 4" SS BSCS

8 qty. 3/8" SS Nylock Nut

16 qty. 3/8" SS Flat Washer

Tools List

- 7/16" Drill bit
- 9/16" Socket
- 9/16" Wrench
- 7/32" Hex Key
- Level
- Impact Gun (Optional)
- Drill

1. Drill plastic out of the mounting holes on the seat, braces and stands using a 7/16" dia. drill bit.
2. Fasten the seat to the stands loosely using fixings provided.
3. Fasten the brace to the stands and seat loosely.
4. Make sure the bench is level and tighten all the bolts.
5. Place the bench in its final location and mark out base holes.
6. Move the bench to a safe location and drill holes.
7. Move bench back in place and anchor down using appropriate fixings for the ground material.

Periodic check of bolts tightness recommended



PREMIER POLYSTEEL

The Best Commercial Outdoor Furniture Available. Period.

